

Room #	Item & Location
244	North Wall - joint visible 2 feet from top of ceiling West Wall - cover plate above door does not cover entire North Wall - outlet 244-04 needs touch up paint above Light out above door Curtain off one hook Outlet box on East Wall
243	paper in ceiling tile at vent box above door does not cover hole 2 dents in door cabinet needs to be moved outlet west wall drywall need work threshold does not seal properly
245	Curtain off one hook cover plate missing at G-line
246	cover plate missing at G-line Caulk ceiling track at column box above door does not cover hole ceiling tile not cut right above door - replace it remove blue tape stuck to ceiling grid on north wall above Door seal along door hinge needs to sit better or be replaced
247	cover plate missing at G-line door frame paint
248	tv mounted crooked loose plate holes in wall behind tv cover plate missing at G-line door frame scraped door scraped stain in light cover close to south wall door seal needs to be readjusted
250	cover plate missing at G-line dry wall smoothness - south wall paint on seals
SAPF Exit Door	gap at bottom of door does not seal install crash bar
SAPF Kitchen	far left counter drawer cannot be opened - counter near fridge rubs under top cabinet because it does not fit water for coffee not hooked up safe needs to be moved switch - does not operate/cabinet covers sign and switch
SAPF Electrical Room	Fire piping not painted or marked Rag on conduit over door electrical panel not marked

- electrical panel door needs to be readjusted
- fire conduit not painted, needs attention
- missing cover for FPE junction box
- paint touch up on northwall
- perimeter of floor needs attention
- insulation coming off of ductwork
- tape on electrical box
- general condition of drywall - not to roof (1/2" gap, no c
- transformer not square or bolted down
- string hanging off of conduit
- drywall not taped/jointed behind NorthEast column
- Rear side of South East column not painted
- Paint all wall conduit color of wall
- SAPF East bathroom adjust sink sensitivity
- paint on tile
- SAPF West Bathroom adjust sink sensitivity
- paint door edge - it is rubbing frame
- adjust light
- SAPF hallway hall heater a mess
- paint door frames
- hallway light out next to kitchen
- 242 missing cover at east wall
- missing ceiling tile in corner
- ceiling tile stained at sprinkler head
- cabinet needs to be moved at door
- paint around outlets
- ceiling tile sensor tile does not fit
- outlet cover above door does not fit
- SAPF Main Conference Room South wall needs to be wiped down
- debris in light cover on south east side of room column
- east wall missing cover plate
- shelf cabinets cover switch and outlets
- ceiling tile nicked
- west wall missing outlet cover
- plaster needs to be moved
- SAPF hallway adjacent to man trap
- replace ceiling tile on west wall with sprinkler head
- door frame paint
- SOU Room move desk, move safe
- conduit going through floor not sealed
- electrical panel not marked
- 236 conduit above door
- sprinkler head covered with foil
- sprinkler pipe not marked/painted - fire conduit needs c
- base molding
- hanging flexible conduit
- shelves need to be moved

- VAV making loud noises
- hole in north wall above 2nd gray conduit line labeled D
- door edge needs to be repainted
- 249 missing outlet covers on south and east wall
- safe and desk need to be moved
- carpet loose
- transition at comm room
- COMM room off 249 pipe not painted - remove cover on sprinkler head
- electrical panel not labeled
- threshold not installed
- east wall needs to be repainted
- remove string
- hole in west wall
- mechanism on top of door to pull door closed was unusable
- hole through wall - passage to mechanical room
- fire caulk ground to mechanical room
- 232 blood on curtain side facing door
- crooked outlet on south wall
- move safes and furniture
- no hardware on drawers
- trim and seal for window
- counter top does not allow top drawers to open
- missing outlet cover on north wall
- crooked light switch cover
- need touch up paint along door frame
- paint around outlet on west side of north wall under counter
- Mantrap pass through drawer not flush
- paint under window frame
- glass panel - missing cover
- fit of ceiling tile
- 234 move shelves
- ceiling tile conduit
- hole in ceiling tile
- base molding
- 233 all desk needs to be moved
- blocked by cabinet air control
- holes in ceiling tile at door
- cover over door not covering hole
- hidden light switch
- threshold cleaning
- mechanical room all fire conduit needs cleaned and painted red and labeled
- hole in floor
- ground passes through SAPF barrier - no caulk
- condensate drains need to be centered over drain, replace
- conduit through floor needs sealant
- refrigerant lines not caulked
- check lines at south wall

- frame tag painted on fire door/broken hinge screw
- open covers throughout
- hole in concrete block on west wall below fire junction
- hole in drywall along north wall in NW corner
- tear in insulation coming out of duct leaving west side of
- tear in insulation on top of duct coming out of unit along
- cut all thread coming from unistrut
- 227 general cleaning of wall
- move furniture out of way
- 229 move furniture out of way
- 201 paint on wall
- move furniture out of way
- light covers need to be cleaned
- clean window/sill
- Hallway near elevator paint on outlets - top of all corner covers
- clean light covers, clean around elevator doors
- replace ceiling tile containing unit 1-111
- damaged tile near electrical room
- elevator mechanical room re-paint inside of door
- missing covers
- hole in wall on east wall - penetration not sealed
- unplugged item in south west corner
- fire pipe not painted and cap on head
- condensate line
- elevator door gap at bottom
- 226 paint on carpet
- missing ceiling tile in corner
- 225 door does not shut, rubbing on bottom
- floor covering on platform
- exit signs - change direction 90 degrees
- fridge doesn't fit
- paint on counter top
- G-line wall major hump in wall
- ceiling tile pushed up
- corners need paint
- hole above door west side needs cover
- paint on base molding
- helmet shelving need to fill screwheads/finish
- water to coffee not hooked up
- install carpet tile for ready officer desk area
- counter doors need rubber stops so it doesn't bang loud
- COMM room fire conduit taped over
- fire pipe not painted, spary head covered
- Women's bathroom sprinkler head covered with foil
- mirror needs to be centered over sinks
- grout missing
- caulking needed in shower/corners

- paint on tile at window/paint on window
- handicap shower higher than floor - drainage issue
- no shower curtains
- caulk between tile and shower
- no caulk under window ledge
- base tile under sinks dirty
- loose towel holder on north shower
- Men's Bathroom No T-Support for urinal partitions
- tile needs to be cleaned
- paint on window
- no caulk under window ledge
- screws in partition doors not screwed in all the way or v
- benches not positioned properly at lockers
- dent in trash receptacle
- showers not caulked
- handicap shower floor higher than finish floor
- pull plastic off wall cover at shower
- loose and dirty towel holders on north shower
- clean tile below sinks on west wall
- janitor address blue tape
- drain cover
- paint on ceiling
- sprinkler escutcheon not flush with ceiling tile
- repair wall next to sink on north wall
- 223 light cover loose
- ceiling tiles stained from water leak
- move furniture
- 224 ceiling tile doesn't fit right
- multiple stained ceiling tiles
- 209 gap at sink and backsplash
- ceiling tile doesn't fit right
- base cove behind door needs to be replaced
- 221 move furniture from walls
- ceiling tile doesn't fit right
- ceiling tile in northeast corner needs to be replaced
- 220 move furniture from walls
- ceiling tile at sprinkler head
- escutcheon plate needs to be realigned
- damaged ceiling along west wall
- touch up paint on walls
- 208 paint on base molding
- ceiling tile rough edge
- replace damaged ceiling tiles
- one light missing/burned out
- 210 move furniture from walls
- CO Bathroom not complete or ready for inspection
- 212 paint door frames

- ceiling tile stained
- tv crooked/placement
- table center cover
- light covers need cleaning
- cabinet hinges loose
- remove bags of rocks in conference table
- 213 install outlet on north wall and est wall
- install cover for table
- address ceiling tiles
- big hold in wall, no cover
- move tvs up a foot
- 214 holes in wall behind tv
- install whiteboard
- install outlet on north wall
- tv box cover
- cabinet hinges loose
- door paint
- Electrical Room touch up paint on walls
- put in fire extinguisher
- transformer not square or bolted down
- mechanical room, west side no caulk in floor passenger/conduit
- three bottles of urine in corner with trash
- fire caulking
- paint beam
- base molding epoxy covered
- fire piping not red
- air vent missing cover
- safety railing needs to be removed from ladder
- covered sprinkler head
- ground bar
- all passages through wall and floor need caulking
- replace floor drain cover
- base molding not behind duct return
- fire sprinkler pipe not painted red
- dry wall in corner
- unit 1 not 100% bolted to pad
- west wall bracket not attached to wall between AHU
- vacuum line back of AHU 1 not connected
- flex conduit - escaping air flow
- flex conduit not attached to unit
- repaint outside of door that leads to outside porch
- wide gap in door leading to outside
- two gang boxes installed on top of each other improper
- need protective covers for sprinkler heads
- remove temporary lighting above duct work
- door hardware and seal missing at exit door
- vac lines and conduit insulated at trunk

- supports not attached to floor - one does not reach floor
- beam needs painting - structural
- trash on floor behind AHU 1
- gap in drywall at roof SW top corner
- west wall line pass through not fire caulked at AHU 2
- 219 move furniture
  - base molding in corner
- 219A stained ceiling tile
  - light cover needs cleaning
  - move cabinets from wall
  - loose door hardware
- 222 move furniture from walls
- 217 move furniture from walls
  - tv in way of cabinet
  - paint on frame at window
  - ceiling tile stain
- 218 ceiling tile stain
  - clean light covers, clean around elevator doors
  - move furniture
  - heater cover loose and damaged
- Exit door seal damaged
  - grout cracking and sloped into doors
- general notes hall paint in corners
  - all hall corner guards need cleaning and tightening
  - multiple instances of where furniture was not moved fr

re hole  
it

ve tvs  
laced so door can close properly

ds to be shimmed

h plate



corner

cleaning

DC

ttached

unter

ed

ace cover

30X

f unit along south wall  
g north wall on east side

fly when closed

wrong size



r

om wall for inspection